

RECEIVED  
JAN 17 1991

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
Telephone: (801) 538-5340  
Fax: (801) 359-3940

DIVISION OF  
OIL, GAS & MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. GENERAL INFORMATION

1. Report Time Period: From (mo./yr.) 1/90 To (mo./yr.) 12/90
2. DOGM File Number (original notice): M / 047 / 010
3. Mine Name: BONANZA MINES
4. Legal Description (Location of Lands Affected): SEE ATTACHED SHEET  
     1/4,      1/4, Section     , Township     , Range       
     1/4,      1/4, Section     , Township     , Range       
     1/4,      1/4, Section     , Township     , Range
5. Mineral(s) Mined: GILSONITE
6. Name of Operator or Company: AMERICAN GILSONITE CO.
7. Permanent Address: BONANZA UTAH 84008

8. Company Representative (or designated operator):

Name: COLE HACKING

Title: SAFETY/ENVIRONMENTAL ENGINEER

Address: BONANZA MINE SITE BONANZA UTAH 84008

Phone: (801) 789-1921 EXT-32

- ☐ Please check if any of the above information has changed since previous year.

II. MINING AND RECLAMATION

1. Was the mine active during the past year? Yes ☒ No ☐

2. If active, how much ore or mineral was mined? 29,000 TONS

3. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, volume of material moved, and the acreage affected.

2.5 Acres at E-30 mine site, for 3 settling ponds, 1 Acre at E-28 Escape shaft, area was cleared of vegetation hoist and derrick located at site  
LE-7 Escape shaft, area cleared of vegetation, hoist and derrick located at site.

4. Briefly describe the reclamation work performed during the past year. This description should include acreage reclaimed, methods employed, and an evaluation of the results.

40 Acres were reseeded using a seed drill method on 11-19-90, 11-21-90  
no results have been achieved as yet.

5. What was the total unreclaimed acreage at years end? 115.4

6. Briefly summarize mining and reclamation planned for the upcoming year.

MINING WILL CONTINUE IN THE AREAS WE ARE NOW MINING.

NO RECLAMATION IS PLANNED IN THE FISCAL YEAR 1991.

**NOTE:** Section III., "Additional Information" applies only to large mining operations.

### III. ADDITIONAL INFORMATION

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

### IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

N. H. Kunz

Title of Operator:

Acting Operations Mgr

Signature of Operator:

N. H. Kunz

Date: 1/23/91

jb  
MR-AR

RECEIVED  
JAN 28 1991

DIVISION OF  
OIL, GAS & MINING